IN THE DRAWINGS

Please amend the drawings as follows:

In FIG. 1, please add reference numeral "20" in FIG. 1.

In FIG. 3, please change "db" to --dB--; please increase the signal of MSi at time t₂ above line MSN; and please increase the signal of MSO at time t₃ above line MSN.

In FIG. 7, please change "PARALLEL SIGNAL CHANNEL" to --T/P RATIO INFORMATION--;

please delete the arrow from "T/P RATIO INFORMATION" to the traffic space between time t_1 and t_2 above;

please insert an arrow from "T/P RATIO INFORMATION" to the T/P ratio space between time t₀ and t₁; and

please mark the area corresponding to the PACKET DATA CHANNEL.

In FIG. 8, please mark the area corresponding to the PACKET DATA CHANNEL.

In FIG. 9, please change the text in box 88 to --DATA RATE CORRELATOR--.

Attorney Docket No.: 010011

Customer No.: 23696


- 28

MSN



20

010011; LUNDBY et al. Sheet 1/10



Channel

FIG. 1







FIG. 2

Sheet 2/10








010011; LUNDBY et al. Sheet 4/ 10




010011; LUNDBY et al. Sheet 5/10









010011; LUNDBY et al. Sheet 9/10




FIG.10

01001T; LUNDBY et al. Sheet 10/10




FIG.11